



LuK Service Info



Modified sealing of the guide tube

Sealing ring now included separately in the package

Manufacturer: VW-Gruppe

Gearbox: MQ 250

Part no.: 414 0024 10

See parts catalog for current assignment



Figure 1: Guide tube 414 002410 with separate sealing ring

The sealing concept of the release bearing guide tube for the MQ 250 gearbox from the VW Group has been revised. Previously, the guide tube was supplied with a permanently bonded sealing ring. This version is no longer produced. It will be replaced by a new variant.

In the new version (figure 1), the sealing ring is supplied separately. This must be installed on the gearbox side of the guide tube prior to installation. It is not permitted to use any additional sealant.

Previous guide tubes from old stock conform to the technical specifications and can be used without any concerns.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REP>XPERT