



## LuK Service Info

# Part Nr. 231 0105 11 – 310/310mm KGS6

Manufacturer: CASE IH, NEW HOLLAND, STEYR

Model: FARMALL 105A, 115A

JX90, 95, JX1070U, 1080U, 1090U, 70U, 80U, 90U, 95, JXU105, 75, 85, 95

5635, 6635, 7635, L75, L85, T4.105, T4.75, T4.85, T4.95, T5030, T5040

, T5050, T5060, TD5040, TD5050, TD5.105, TD5.110, TD5.115,

TD95D, TL100A, 70, 70A, 75, 80, 80A, 85, 85E, 90, 90A, 95, 95A, TL Brazil

4000 KOMPACT

Art.-Nr.: 231 0105 11

Info: 231 0105 11 replaces / ersetzt /  
replace / sustituye a / sostituisce  
231 0105 10



TB1206



631 3060 19 = 231 0105 11 + 331 0220 10

631 3060 12 = 231 0105 11 + 331 0220 10 + 500 0459 00 + 500 1292 40 + 410 0025 40

631 3060 13 = 231 0105 11 + 328 0332 10 + 500 0459 00 + 500 0284 40 + 410 0025 40

631 3173 09 = 231 0105 11 + 328 0664 10

631 3173 00 = 231 0105 11 + 328 0664 10 + 500 0459 00 + 500 0284 40 + 410 0025 40



231 0105 10

OE 8771 6719



231 0105 11

OE 8447 8095

Call : +44 (0) 1432 264264

vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER  
REP>XPERT